

CONTENT

1

2

2

4

4

5

6

6

7

7

8

8

8

使用时注意事项





保养方法

常见故障分析及排除

注:当您的机器故障状况用上述方法不能

major contribution to destroy used documents and help you correctly use the shredder and prevent losses, please read this manual carefully.

Useage attention

Warning

※ Otherwise there is the possibility



Do not handle power plug by wet hands.
※ Otherwise there is the possibility of electric shock.



※ Otherwise there is the possibility of fire or electric shock.



Do not sprinkle water to the shredder.
※ Otherwise there is the possibility of fire or electric shock.

Do not put the shredder beside any heating or cooling equipment or in a place where there is high temperature, excessive moist or lots of dust.

※ Otherwise there is the possibility of breaking the machine.



※




In case of abnormal operation such as emission of smoke odor, please stop using the shredder.

※ Otherwise there is the possibility of fire or electric shock.



If the shredder and power cable have any breakage, please do not use it.

※ Otherwise there is the possibility of fire or electric shock.



y
sing.
on

ion
ore

Maintenance

Trouble Analysis & Troubleshooting

In case the above solutions are

